



## Scarboro Landfill Aerial View Sept 25, 2007 6PM

Masses of white areas are unknown powder chemical waste from JM Huber of Havre de Grace, MD. Large clouds form at dumping and it sits uncovered indefinitely.

Exposed trash sits outside alternate daily cover material.

All white "specks" are large areas of uncovered trash as shown in closeup photos of corresponding areas. Grooves in banks show erosion and instability.



Facing Scarboro Rd.



South side of landfill facing homes on Sandy Hook Rd.



--- Area of uncovered open trash, in violation of MDE operating permit, public health hazard.  
--- Area of trash being covered. Note only area facing and visible from Scarboro Rd. is being covered.

Aerial photos by Laurie Harroll,  
Land photos by Leslie Rutherford on  
Aug 29, 2007