

**Dozens of acres of uncovered trash and other operating permit violations at
Scarboro Landfill, Harford County, MD**



August 29, 2007 Scarboro Landfill south side. Approximately 150 feet of uncovered trash.



August 29, 2007, Scarboro Landfill south side. Trash never covered – can see workmen at top of ridge – they are working on what can be seen from face – trash just dumped on this side to get out of view.



Above, August 29, 2007. Scarboro Landfill south side. Shows steepness of slope. Slope is suppose to be 3:1 this looks approximately 1.5:1 – plus uncovered trash and blown litter.



Left, August 29, 2007, Scarboro Landfill south side. Pile of uncovered trash – never covered – mattresses etc.



Above, August 29, 2007, Scarborough Landfill south side. Uncovered trash, erosion and spots of leachate.



Left, August 29, 2007 Scarborough Landfill south side 013 Metal road sign and other trash never covered just lying in pile with weeds growing all around it.



Above, August 29, 2007, Scarborough Landfill south side. Pile of uncovered trash – including metal – just right over bank out of view from face.

Left, August 29, 2007. Scarborough Landfill, south side. Very deep erosion not stabilized and uncovered trash.